

Os chassis envolvidos são:

K 1600 GTL

WB10F0202KZ529201
WB10F0204KZ529202
WB10F0204KZ529250
WB10F0209KZ529308
WB10F0200KZ529309
WB10F0207KZ529503
WB10F0209KZ529504
WB10F0200KZ529505
WB10F0208KZ529512
WB10F020XKZ529513
WB10F0201KZ529514
WB10F0203KZ529515
WB10F0205KZ529516
WB10F0206KZ529539
WB10F0202KZ529540
WB10F0203KZ529546
WB10F0200KZ529553
WB10F0207KZ529565
WB10F0209KZ529566
WB10F0200KZ529567
WB10F0204KZ529572
WB10F0206KZ529573
WB10F0200KZ529598
WB10F0202KZ529599
WB10F0205KZ529600
WB10F0207KZ529601
WB10F020XKZ529608
WB10F0200LZ530462
WB10F0204LZ530481
WB10F0205LZ530621
WB10F0207LZ530622
WB10F0205LZ530652
WB10F0204LZ530657
WB10F0205LZ530716
WB10F0200LZ530719
WB10F0207LZ530801

K1600 Bagger

WB10F5100LZG14816
WB10F5102LZG14817
WB10F5101LZG14825
WB10F5107LZG14845
WB10F5100LZG14881
WB10F5103LZG15068
WB10F5101LZG15070
WB10F5103LZG15071
WB10F510XLZG15116
WB10F510XLZG15181
WB10F5103L6D11661